DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-009318 Address: 333 Burma Road **Date Inspected:** 30-Sep-2009

City: Oakland, CA 94607

OSM Arrival Time: 645 **Project Name:** SAS Superstructure **OSM Departure Time:** 1845 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Xu Xian Ping No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

OBG & TOWER Components **Bridge No:** 34-0006 **Component:**

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Sandeep Kumar was present during the times noted above for observations relative to the work being performed.

BAY 2

This QA Inspector observed the following work in progress:

SMAW process Tack welding of weld joint # 011 located on Floor Beam FB3027 - 001. Welder is identified as 045251. ZPMC QC is identified as Zhang Hai Feng. The welding variables recorded by QC appeared to comply with the WPS -B - P - 2112.

FCAW process welding of weld joint #022 located on Floor Beam FB3051 – 001. Welder is identified as 045203. ZPMC QC is identified as Yang Qing Feng. The welding variables recorded by QC appeared to comply with the WPS - B - T - 2132 - 3.

FCAW process welding of weld joint #050 located on Floor Beam FB3089 – 001. Welder is identified as 203871. ZPMC QC is identified as Yang Qing Feng. The welding variables recorded by QC appeared to comply with the WPS - B - T - 2132 - 3.

WELDING INSPECTION REPORT

(Continued Page 2 of 4)

SAW process welding of weld joint #006 located on Super (Deck) Panel 10BW – SEG61. Welder is identified as 250270. ZPMC QC is identified as Xiang Feng Feng. The welding variables recorded by QC appeared to comply with the WPS - B - T - 2221 - B - L2c - S -2.

FCAW process welding of weld joint #042 located on Floor Beam FB3051 – 001. Welder is identified as 045203. ZPMC QC is identified as Yang Qing Feng. The welding variables recorded by QC appeared to comply with the WPS - B - T - 2133.

BAY 3

Green Tags

The following green tag issued for OBG component after completing the NDT requirements are: FB023 – 010 – Green Tag # 10710

This QA Inspector observed the following work in progress:

FCAW process welding of weld joint #104 located on CSD4 – PP100. Welder is identified as 208035. ZPMC QC is identified as Gui Yuan Ting. The welding variables recorded by QC appeared to comply with the WPS – B – T -2232 - Tc - U4b - F.

FCAW process welding of weld joint #034 located on X-37 stiffener CA081. Welder is identified as 044790. ZPMC QC is identified as Gui Yuan Ting. The welding variables recorded by QC appeared to comply with the WPS - B - T - 2233 - Tc - U4b - F.

FCAW process welding of weld joint #103 located on CSD4 – PP098. Welder is identified as 208035. ZPMC QC is identified as Gui Yuan Ting. The welding variables recorded by QC appeared to comply with the WPS – B – T -2132-3.

FCAW process welding of weld joint #057 located on X-37 stiffener CA087. Welder is identified as 044790. ZPMC QC is identified as Gui Yuan Ting. The welding variables recorded by QC appeared to comply with the WPS - B - T - 2233 - Tc - U4b - F.

BAY 5

Magnetic Particle Testing

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. The member is identified as OBG Components. The weld designations reviewed are as follows:

1. TR 8B – PP8.5 – 003; 004

WELDING INSPECTION REPORT

(Continued Page 3 of 4)

Ultrasonic Testing

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member is identified as OBG Component. The weld designations reviewed are as follows:

1. TR 8B – PP8.5 – 003; 004 – Green Tag # 009780

This QA Inspector observed the following work in progress:

SMAW process Tack welding of weld joint # 007 located on Bike Path BK001 – 024. Welder is identified as 215083. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the WPS -B - P - 2113.

BAY 6

Tower

This QA Inspector observed the following work in progress:

SMAW process welding of weld joint #1A located on Tower Strut WD1 – A305 – 53M – 4. Welder is identified as 067707. ZPMC QC is identified as Zhao Chen Sun. The welding variables recorded by QC appeared to comply with the WPS -485 - SMAW - 2G(2F) - FCM - Repair - 1.

Cross Beam - 8

This QA Inspector observed the following work in progress:

SMAW process Tack welding of weld joint #094 located on Cross Beam CB202G – 018. Welder is identified as 070007. ZPMC QC is identified as Liu Chuan Gang. The welding variables recorded by QC appeared to comply with the WPS -B - P - 2112.

FCAW process welding of weld joint #017 located on Cross Beam CB202G – 008. Welder is identified as 220068. ZPMC QC is identified as Liu Chuan Gang. The welding variables recorded by QC appeared to comply with the WPS - B - T - 2232 - TC - U4b - F.

SMAW process Tack welding of weld joint #092 located on Cross Beam CB202G – 018. Welder is identified as 070007. ZPMC QC is identified as Liu Chuan Gang. The welding variables recorded by QC appeared to comply with the WPS -B - P - 2112.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No Relevant Conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or

WELDING INSPECTION REPORT

(Continued Page 4 of 4)

remedial efforts please contact Eric Tsang - 15000422372, who represents the Office of Structural Materials for your project.

Inspected By:	Kumar,Sandeep	Quality Assurance Inspector
Reviewed By:	Whitehead,Lonnie	QA Reviewer